



Heartland Asbestos Inventory

BLDG #103 4300 GOODFELLOW BLVD. ST. LOUIS MO

[MO0606]

Inspected For GSA By: Tetra Tech Inc

Date: 5/25/2003 1:25:02 PM

Page 1 of 2

| Floor Number | Location | Material | Condition | Quantity | Asbestos? |
|--------------|----------|---------------------------------------|-----------|------------|-----------|
| 001 | 223 | TSI tank insulation | Good | 140 Sq Ft | Yes |
| 001 | 228 | 12" FT tan w/ brown and white streak | Good | 2000 Sq Ft | Yes |
| 001 | 230 | 12" FT tan w/ brown and white streak | Good | 600 Sq Ft | Yes |
| 001 | 231 | 12" FT tan w/ brown and white streak | Good | 800 Sq Ft | Yes |
| 001 | 232 | 12" FT tan w/ brown and white streak | Good | 700 Sq Ft | Yes |
| 001 | 236 | 12" FT tan w/ brown and white streak | Good | 150 Sq Ft | Yes |
| 001 | 245 | 12" FT tan w/ brown and white streak | Good | 1400 Sq Ft | Yes |
| 001 | 249 | 12" FT tan w/ brown and white streak | Good | 2200 Sq Ft | Yes |
| 001 | 249 | 12" FT tan w/ brown and white streak | Good | 2400 Sq Ft | Yes |
| 002 | 252 | 12" FT tan w/ brown and white streak | Good | 1900 Sq Ft | Yes |
| 002 | 256 | 12" FT tan w/ brown and white streak | Good | 700 Sq Ft | Yes |
| 002 | 258 | 2 x 4 CT small irreg gouges 2 sz hole | Fair | 7000 Sq Ft | Yes |
| 002 | 259 | 12" FT tan w/ brown and white streak | Good | 1200 Sq Ft | Yes |
| 002 | 260 | 2 x 4 CT small irreg gouges 2 sz hole | Fair | 9800 Sq Ft | Yes |
| 002 | 261 | 12" FT tan w/ brown and white streak | Good | 150 Sq Ft | Yes |
| 002 | 262 | Steam lagging (old) | Fair | 12 Ft | assumed |
| 002 | 262 | 12" FT tan w/ brown and white streak | Good | 85 Sq Ft | Yes |
| 002 | 262 | Steam fittings (old) | Good | 9 Fittings | assumed |
| 002 | 263 | 12" FT tan w/ brown and white streak | Good | 400 Sq Ft | Yes |
| 002 | 264 | 12" FT tan w/ brown and white streak | Good | 100 Sq Ft | Yes |

[Click Here for Next 20 Records](#)



Heartland Asbestos Inventory *(cont.)*

BLDG #103 4300 GOODFELLOW BLVD. ST. LOUIS MO

[MO0606]

Inspected For GSA By: Tetra Tech Inc


Date: 5/25/2003 1:25:02 PM


Page 2 of 2

| Floor Number | Location | Material | Condition | Quantity | Asbestos? |
|--------------|----------|---------------------------------------|-----------|------------|-----------|
| 002 | 265 | 12" FT tan w/ brown and white streak | Good | 480 Sq Ft | Yes |
| 002 | 265 | 2 x 4 CT small irreg gouges 2 sz hole | Good | 480 Sq Ft | Yes |
| 002 | 266 | 12" FT tan w/ brown and white streak | Good | 440 Sq Ft | Yes |
| 002 | 267 | 12" FT tan w/ brown and white streak | Good | 225 Sq Ft | Yes |
| 002 | 267 | 2 x 4 CT small irreg gouges 2 sz hole | Good | 3750 Sq Ft | Yes |
| Bsmnt | 222 | TSI debris in soil - crawlspace | Poor | | Yes |

(b) (7)(F)


Source Modified from Federal Center Campus, 1998



| | | |
|--|--|---|
| <p>Federal Center Building 103 4300 Goodfellow St. Louis, Missouri 63120</p> | <p>Figure XX Site Layout Map Plan A - First Floor</p> | <p> Tetra Tech EM Inc.</p> <p><small>THE SOURCE Open to the Public Revision 0100 11/01/03</small></p> |
|--|--|---|

Scanned from Federal Center Complex, 1998

(b) (7)(F)



| | | | |
|---|---|--|--------------------------------------|
| <p>  Tetra Tech EM Inc. <small>Owner: Shaw Group Project: 010021101020</small> </p> | <p> Figure XX Site Layout Map Plan B - Second Floor </p> | <p> Federal Center Building 103 4300 Goodfellow St. Louis, Missouri 63120 </p> | <p> Total 5/21/00 </p> |
|---|---|--|--------------------------------------|