



"Mary Erio"
<ntap@igc.org>

08-12-2003 13:24

To: "Paulette Detillier" <pdetillier@erasafety.com>
cc: david.hartshorn@gsa.gov, michael.crocker@gsa.gov
Subject: Goodfellow Day Care Map

Paulette:

Attached is the inspection map from the Goodfellow day care center. Let me know if you have any questions.

Mary Erio

Evaluation of peeling paint on ceiling located above drop ceiling
Building 104E - Plaza Level
Mary J. Erio, PE, CIH, CSP
for GSA

UNCLE SAM'S KIDS

(b) (7)(F)



Inspection Notes 12/06/03

1. Entire room was shaded if over 50% of paint area above ceiling was peeling.
2. Shaded area = approx 3600 ft².
3. Fire walls observed between all rooms, and between hallway and rooms, with some perforations.
4. Sections of hallway and rooms are divided by beams above ceiling running across building width every 30 feet.
5. In unshaded areas, either no peeling paint or only small patches were observed.
6. Ceiling above some areas was difficult to see because of ductwork, inc. main kitchen, restrooms between rooms, and hallway.
7. Ductwork generally approx. 4 feet below below painted ceiling except for kitchen.
8. Laundry room was not accessible.
9. Some paint chips were observed on top of ceiling tiles, mainly red and orange rooms.
10. Approx. 4 water stained ceiling tiles were observed in purple room, 2 in pink room.

Plaza Area