



EnviroHealth Technologies Inc.

Laboratory & Consulting Services

Report No. 02-04-01143

April 30, 2002

Determination of hazardous waste characteristics on two (2) samples submitted on April 24, 2002.

General Services Administration
1500 Bannister Road
Kansas City, MO 63048

Attn: Mr. William Ferreter

TEST REPORT

Project Name: GSA, 4300 Goodfellow, At Parking Lot C
Project Number: EHT-02038
Collected By: Jerry Dissault
Collection Date: April 24, 2002

Toxicity Characteristic Leaching Procedure (TCLP) - Lead

| <u>Sample Identification</u> | <u>EHT No.</u> | <u>Analysis</u> | <u>Result, mg/L</u> | <u>Limit, mg/L</u> |
|--|----------------|-----------------|---------------------|--------------------|
| North Side of Demolition Dirt/Rock/Concrete Pile | 41682 | Lead | <0.2 | 5 |
| South Side of Demolition Dirt/Rock/Concrete Pile | 41683 | Lead | <0.2 | 5 |

Extraction Date: April 24-25, 2002
Analysis Date: April 29, 2002
Reporting Limit: 0.2 mg/L
Method Reference: SW846 1311/7420

Analyst: ELS

Respectfully submitted,

(b) (6)

William J. Lowry, CIH
President

Page 1 of 2

3830 Washington Blvd. • Suite 123 • St. Louis, Missouri 63108 • (314) 531-9868 • Fax (314) 531-9196