

Appendix B



Photograph 1. Building 105 SAFR. Bullet Pit, September 2002.



Photograph 2. Building 105 SAFR. Bullet Pit, September 2002.



Photograph 5. Building 105 SAFR. Typical staining on floor, September 2002.



Photograph 6. Building 105 SAFR. Plastic sheeting containment with clean air HEPA filters at left, September 2002.



Photograph 7. Building 105 SAFR. Column at right hand (NE) corner of containment, September 2002.



Photograph 8. Building 105 SAFR. Containment ledge drops off to floor with sump, September 2002.



Photograph 3. Building 105A SAFR. Debris behind Bullet Pit, September 2002.



Photograph 4. Building 105 SAFR. Ledge above Bullet Pit to the left, September 2002.