

There is no record of inspection for the fixtures/filters listed below for the planned inspection date. GSA is working with maintenance contractor to ensure all filters are inspected and inspections are logged accordingly.

Outlets w/Filters that are not included in the log

Planned Date	Asset Number	Publication Description
11/6/2023	2944258	5W-1 Women's Restroom East - Lavatory Faucet-Right
11/6/2023	2944257	5W-1 Women's Restroom East - Lavatory Faucet-Center
11/6/2023	2944256	5W-1 Women's Restroom East - Lavatory Faucet-Left
11/6/2023	2944249	5M-1 Men's Restroom East - Lavatory Faucet-Right
11/6/2023	2944248	5M-1 Men's Restroom East - Lavatory Faucet-Left
11/6/2023	2944240	C507 Janitor's Closet - Mop/Slop Sink
11/6/2023	2944218	C407 Janitor's Closet-Mop/Slop Sink
11/6/2023	2944082	1W-2 Women's Restroom South - Lavatory Faucet-Right
11/6/2023	2944081	1W-2 Women's Restroom South - Lavatory Faucet-Left
11/7/2023	2944419	Suite. 540 Kitchenette - Faucet
11/7/2023	2945147	Suite 540 CBP Open Area Kitchenette - Faucet (507-15)
11/7/2023	2944416	Suite 608 Kitchen - Faucet
11/7/2023	2944260	Suite 520 Kitchenette Faucet (508-13)
11/8/2023	2944222	Suite 415 Kitchenette - Faucet (N)
11/8/2023	2944163	234 Kitchen Faucet (209-04)
11/8/2023	2944092	119-07 Toilet/Sink Combo-Left
11/8/2023	2944091	119-10 Toilet/Sink Combo
11/14/2023	2944419	Suite. 540 Kitchenette - Faucet
11/14/2023	2945147	Suite 540 CBP Open Area Kitchenette - Faucet (507-15)
11/14/2023	2945143	Suite 615 Break Room-Kitchen Faucet (607-06A) A (Second fixture)
11/14/2023	2945145	Suite 620 Break Room Kitchen - Faucet (608-12A) A (Second fixture)