

KCORP Federal McNamara Building Domestic Water Testing November 2023

Sample #	Sample Location	Outlet Type	Copper (ppb) AL: 1300 ppb	Lead (ppb) AL: 15 ppb	E. Coli	Total Coliform	Legionella (CFU/mL)	Legionella Species
1	Basement Drinking Fountain 4E	Drinking fountain	280	1	NEGATIVE	NEGATIVE	0.8	non pneumophila
2	Basement B105 Restroom (1)	Restroom sink	90	ND	NEGATIVE	NEGATIVE	2.8	serogroup 2-14
							2	non pneumophila
3	Basement 3E Gym Mens Shower #2	Shower	30	ND	NEGATIVE	NEGATIVE	NLI	
4	Basement Gym Drinking Fountain	Drinking fountain	320	ND	NEGATIVE	NEGATIVE	NLI	
5	1st Floor Drinking Fountain O4	Drinking fountain	450	ND	NEGATIVE	NEGATIVE	NLI	
6	Basement Gym Womens B104	Restroom sink	70	ND	NEGATIVE	NEGATIVE	NLI	
7	Basement Drinking Fountain 3E	Drinking fountain	300	ND	NEGATIVE	NEGATIVE	NLI	
8	Basement Mens Bathroom 2M	Restroom sink	20	ND	NEGATIVE	NEGATIVE	NLI	
9	Basement Womens Bathroom 2W	Restroom sink	110	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila
10	1st Floor Bathroom 106	Restroom sink	480	ND	NEGATIVE	NEGATIVE	NLI	
11	Basement Holding Cell (1)	Restroom sink	1600	14	NEGATIVE	NEGATIVE	16.8	serogroup 2-14
		Restroom sink					30	non pneumophila
12	Basement Kitchen Sink 1 (1)	Kitchen sink	90	ND	NEGATIVE	NEGATIVE	0.8	serogroup 2-14
							0.8	non pneumophila
13	Basement Kitchen Sink 2	Kitchen sink	80	ND	NEGATIVE	NEGATIVE	NLI	
14	Basement Kitchen Sink 3	Kitchen sink	120	1	NEGATIVE	NEGATIVE	NLI	
15	GSA Kitchen Sink 12	Kitchen sink	520	ND	NEGATIVE	NEGATIVE	NLI	
16	GSA Bathroom Sink O3	Restroom sink	260	ND	NEGATIVE	NEGATIVE	NLI	
17	14th Floor Drinking Fountain 3E	Drinking fountain	460	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila
18	14th Floor Drinking Fountain 1E	Drinking fountain	280	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila
19	14th Floor Women 1W Sink #1	Restroom sink	50	2	NEGATIVE	NEGATIVE	NLI	
1	14th Floor Women 1W Sink #2	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI	
21	14th Floor Men 4M Sink #1	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI	
22	14th Floor Men 4M Sink #2	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI	
23	13th Floor Drinking Fountain 3E	Drinking fountain	400	2	NEGATIVE	NEGATIVE	NLI	
24	13th Floor Mens Bathroom 4M	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI	
25	13th Floor Womens Bathroom 4W	Restroom sink	20	ND	NEGATIVE	NEGATIVE	NLI	
26	13th Floor Drinking Fountain 2E	Drinking fountain	390	9	NEGATIVE	NEGATIVE	2.4	non pneumophila
27	12th Floor Drinking Fountain 4E	Drinking fountain	260	ND	NEGATIVE	NEGATIVE	NLI	
28	12th Floor Mens Bathroom 4M	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI	
29	12th Floor Womens Bathroom 4W	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI	
30	12th Floor Drinking Fountain 3E	Drinking fountain	370	ND	NEGATIVE	NEGATIVE	0.8	non pneumophila
31	19th Floor Womens Bathroom 3W	Restroom sink	210	ND	NEGATIVE	NEGATIVE	2.8	non pneumophila
32	19th Floor Mens Bathroom 4M (1)	Restroom sink	380	ND	NEGATIVE	NEGATIVE	1.2	serogroup 2-14
							3.2	non pneumophila
33	19th Floor Drinking Fountain 2W	Drinking fountain	380	ND	NEGATIVE	NEGATIVE	NLI	
34	19th Floor Breakroom 113	Breakroom sink	140	ND	NEGATIVE	NEGATIVE	NLI	

KCORP Federal McNamara Building Domestic Water Testing November 2023

Sample #	Sample Location	Outlet Type	Copper (ppb) AL: 1300 ppb	Lead (ppb) AL: 15 ppb	E. Coli	Total Coliform	Legionella (CFU/mL)	Legionella Species
35	19th Floor 111	Restroom sink	20	ND	NEGATIVE	NEGATIVE	NLI	
36	19th Floor 107	Hand sink	270	ND	NEGATIVE	NEGATIVE	NLI	
37	20th Floor Mens Bathroom 4M	Restroom sink	150	2	NEGATIVE	NEGATIVE	NLI	
38	20th Floor Womens Bathroom 3W	Restroom sink	1500	13	NEGATIVE	NEGATIVE	NLI	
39	20th Floor Drinking Fountain 201	Drinking fountain	470	ND	NEGATIVE	NEGATIVE	2.4	non pneumophila
40	20th Floor 1B	Kitchen sink	50	ND	NEGATIVE	NEGATIVE	NLI	
41	20th Floor 218	Kitchen sink	740	2	NEGATIVE	NEGATIVE	3.6	non pneumophila
42	20th Floor 217	Restroom sink	220	ND	NEGATIVE	NEGATIVE	NLI	
43	21st Floor Mens Bathroom 4M	Restroom sink	560	ND	NEGATIVE	NEGATIVE	1.2	non pneumophila
44	21st Floor Womens Bathroom 3W	Restroom sink	4500	9	NEGATIVE	NEGATIVE	17.2	non pneumophila
45	21st Floor 2C	Drinking fountain	320	ND	NEGATIVE	NEGATIVE	NLI	
46	21st Floor 107	Kitchen sink	100	ND	NEGATIVE	NEGATIVE	NLI	
47	22nd Floor Mens Bathroom 4M	Restroom sink	130	ND	NEGATIVE	NEGATIVE	NLI	
48	22nd Floor Womens Bathroom 3W	Restroom sink	200	1	NEGATIVE	NEGATIVE	0.4	non pneumophila
49	22nd Floor 1B	Kitchen sink	110	ND	NEGATIVE	NEGATIVE	NLI	
50	22nd Floor 2C	Drinking fountain	290	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila
51	26th Floor Mens Bathroom 4M	Restroom sink	960	7	NEGATIVE	NEGATIVE	0.4	non pneumophila
52	26th Floor Womens Bathroom 3W (1)	Restroom sink	490	8	NEGATIVE	NEGATIVE	0.4	serogroup 2-14
							1.2	non pneumophila
53	26th Floor 1B	Kitchen sink	40	ND	NEGATIVE	NEGATIVE	NLI	
54	26th Floor 2C	Drinking fountain	250	1	NEGATIVE	NEGATIVE	NLI	
55	26th Floor 211	Restroom sink	330	1	NEGATIVE	NEGATIVE	NLI	
56	26th Floor 308	Restroom sink	140	ND	NEGATIVE	NEGATIVE	NLI	
57	26th Floor 309	Kitchen sink	2400	2	NEGATIVE	NEGATIVE	NLI	
58	8th Floor Womens Bathroom 3W	Restroom sink	60	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila
59	8th Floor 3E	Drinking fountain	250	ND	NEGATIVE	NEGATIVE	0.8	non pneumophila
60	8th Floor 2C02	Drinking fountain	2800	ND	NEGATIVE	NEGATIVE	NLI	
61	Sub Basement Sink	Hand sink	290	ND	NEGATIVE	NEGATIVE	NLI	
62	Mez Mens Bathroom	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila
63	Mez Womens Bathroom	Restroom sink	240	14	NEGATIVE	NEGATIVE	0.8	non pneumophila
64	Mez Drinking Fountain	Drinking fountain	970	10	NEGATIVE	NEGATIVE	12	non pneumophila
65	2nd Floor 2Q-1C	Drinking fountain	140	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila
66	2nd Floor Mens Bathroom Q4-4M	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI	
67	2nd Floor Q3-3C	Drinking fountain	30	ND	NEGATIVE	NEGATIVE	NLI	
68	2nd Floor Womens Bathroom Q3-3W	Restroom sink	40	ND	NEGATIVE	NEGATIVE	NLI	
69	3rd Floor Q1 Room 28	Kitchen sink	710	ND	NEGATIVE	NEGATIVE	NLI	
70	3rd Floor Q4 Room 328	Restroom sink	780	ND	NEGATIVE	NEGATIVE	1.6	non pneumophila
71	3rd Floor Q1-1C	Drinking fountain	270	ND	NEGATIVE	NEGATIVE	NLI	

KCORP Federal McNamara Building Domestic Water Testing November 2023

Sample #	Sample Location	Outlet Type	Copper (ppb) AL: 1300 ppb	Lead (ppb) AL: 15 ppb	E. Coli	Total Coliform	Legionella (CFU/mL)	Legionella Species
72	3rd Floor Mens Bathroom Q1-1M (1)	Restroom sink	300	ND	NEGATIVE	NEGATIVE	0.8	serogroup 2-14
							8	non pneumophila
73	3rd Floor Womens Bathroom Q2-2W (1)	Restroom sink	280	ND	NEGATIVE	NEGATIVE	0.4	serogroup 2-14
							2.8	non pneumophila
74	3rd Floor Q3-3C	Drinking fountain	240	ND	NEGATIVE	NEGATIVE	NLI	
75	4th Floor Q1-1C	Drinking fountain	250	ND	NEGATIVE	NEGATIVE	NLI	
76	4th Floor Q1 Room 113	Restroom sink	150	ND	NEGATIVE	NEGATIVE	NLI	
77	4th Floor Q1 Room 11-1	Shower	670	ND	NEGATIVE	NEGATIVE	NLI	
78	4th Floor Q1 Room 11-2	Shower	470	ND	NEGATIVE	NEGATIVE	NLI	
79	4th Floor Q1 Room 11-3	Shower	560	ND	NEGATIVE	NEGATIVE	NLI	
80	4th Floor Q1 Room 2	Shower	570	2	NEGATIVE	NEGATIVE	NLI	
81	4th Floor Q1 Room 2-5	Shower	2200	4	NEGATIVE	NEGATIVE	NLI	
82	4th Floor Q4 Room 2-S	Shower	5500	3	NEGATIVE	NEGATIVE	NLI	
83	4th Floor Q3 Room 28	Kitchen sink	60	ND	NEGATIVE	NEGATIVE	NLI	
84	4th Floor Q3 Room 25	Restroom sink	20	ND	NEGATIVE	NEGATIVE	NLI	
85	4th Floor Mens Bathroom Q4-4M	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	1.6	non pneumophila
86	4th Floor Womens Bathroom Q3-3W	Restroom sink	50	ND	NEGATIVE	NEGATIVE	7.2	non pneumophila
87	5th Floor Q3-3C	Drinking fountain	340	1	NEGATIVE	NEGATIVE	2	non pneumophila
88	5th Floor Q2-2C	Drinking fountain	300	1	NEGATIVE	NEGATIVE	NLI	
89	5th Floor Q1-1C	Drinking fountain	280	2	NEGATIVE	NEGATIVE	0.8	non pneumophila
90	5th Floor Mens Bathroom Q4-4M	Restroom sink	30	1	NEGATIVE	NEGATIVE	NLI	
91	23rd Floor Mens Bathroom 4M	Restroom sink	440	ND	NEGATIVE	NEGATIVE	NLI	
92	23rd Floor Womens Bathroom 3W	Restroom sink	170	ND	NEGATIVE	NEGATIVE	0.8	non pneumophila
93	23rd Floor Room 1B Pantry	Kitchen sink	50	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila
94	23rd Floor Drinking Fountain 1B	Drinking fountain	220	ND	NEGATIVE	NEGATIVE	0.8	non pneumophila
95	Basement 108 Sink	Restroom sink	500	ND	NEGATIVE	NEGATIVE	NLI	
96	Basement 108 Shower #1	Shower	40	ND	NEGATIVE	NEGATIVE	NLI	
97	Basement 108 Shower #3	Shower	ND	ND	NEGATIVE	NEGATIVE	NLI	
98	Basement 108 Shower #4	Shower	40	ND	NEGATIVE	NEGATIVE	NLI	
99	Basement 104 Shower #1	Shower	190	ND	NEGATIVE	NEGATIVE	NLI	
100	Basement 104 Shower #2	Shower	130	26	NEGATIVE	NEGATIVE	NLI	
101	Basement 104 Shower #3	Shower	160	ND	NEGATIVE	NEGATIVE	NLI	
102	18th Floor Womens Bathroom 2W	Restroom sink	100	ND	NEGATIVE	NEGATIVE	NLI	
103	18th Floor Mens Bathroom 1M	Restroom sink	50	ND	NEGATIVE	NEGATIVE	NLI	
104	18th Floor 1C Drinking Fountain	Drinking fountain	340	ND	NEGATIVE	NEGATIVE	NLI	
105	17th Floor Womens Bathroom 2W	Restroom sink	80	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila
106	17th Floor Mens Bathroom 1M	Restroom sink	40	ND	NEGATIVE	NEGATIVE	NLI	
107	17th Floor 3C Drinking Fountain	Drinking fountain	160	ND	NEGATIVE	NEGATIVE	NLI	

KCORP Federal McNamara Building Domestic Water Testing November 2023

Sample #	Sample Location	Outlet Type	Copper (ppb) AL: 1300 ppb	Lead (ppb) AL: 15 ppb	E. Coli	Total Coliform	Legionella (CFU/mL)	Legionella Species
108	17th Floor 1C Drinking Fountain	Drinking fountain	ND	ND	NEGATIVE	NEGATIVE	NLI	
109	17th Floor 206	Kitchen sink	680	ND	NEGATIVE	NEGATIVE	NLI	
110	17th Floor 212	Kitchen sink	2700	ND	NEGATIVE	NEGATIVE	NLI	
111	18th Floor 065	Kitchen sink	120	2	NEGATIVE	NEGATIVE	NLI	
112	18th Floor 020	Restroom sink	80	2	NEGATIVE	NEGATIVE	NLI	
113	18th Floor 020-H1	Restroom sink	110	1	NEGATIVE	NEGATIVE	2	non pneumophila
114	15th Floor 027	Restroom sink	680	ND	NEGATIVE	NEGATIVE	NLI	
115	15th Floor 3C Drinking Fountain	Drinking fountain	370	ND	NEGATIVE	NEGATIVE	NLI	
116	15th Floor Womens Bathroom 3W	Restroom sink	260	8	NEGATIVE	NEGATIVE	0.4	non pneumophila
117	8th Floor 2C2E	Drinking fountain	550	21	NEGATIVE	NEGATIVE	14.8	non pneumophila
118	8th Floor 1C1E	Drinking fountain	310	3	NEGATIVE	NEGATIVE	1.2	non pneumophila
119	8th Floor Mens Bathroom 4C4M	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI	
120	12th Floor 1E Drinking Fountain	Drinking fountain	260	ND	NEGATIVE	NEGATIVE	0.8	non pneumophila
121	Cooling Tower	Cooling tower					NLI	