

Particulate Readings Log
 Bldg. 104 -VA File Demo

Date	Time	Location	(b) (7)(F)	Visible Condition	Reading (mg/m3)
7/16/2019	14:05	West Egress Hallway at J-11		Hallway was adequately clean	0.031
	14:08	West Egress Hallway at J-13		Hallway was adequately clean	0.036
	14:10	VA Break Room at Col F-9		Adequately clean	0.006
	14:12	VA Cube Space at J-9		Carpeted	0.015
	14:15	VA North entrance to File Space		Critical barrier in place	0.005
	14:18	VA Warehouse at C-9		Typical warehouse, cardboard	0.006
7/17/2019	16:01	West Egress Hallway at J-11		Hallway was adequately clean	0.031
	16:03	West Egress Hallway at J-13		Hallway was adequately clean	0.036
	16:05	VA Break Room at Col F-9		Adequately clean	0.006
	16:06	VA Cube Space at J-9		Carpeted	0.015
	16:08	VA North entrance to File Space		Critical barrier in place	0.005
	16:10	VA Warehouse at C-9		Typical warehouse, cardboard	0.006
7/18/2019	10:25	Break Room at F-9		Clean	0.005
	10:28	Warehouse at C-9		Fireproofing, cardboard	0.009
	10:32	Entry to File Stack removal area		Critical barriers in place	0.006
	10:34	Cubicle Area at J-9		Carpeted	0.007
	10:40	West Egress Hall at J-11		Critical barriers in place	0.012
	10:43	West Egress Hall at J13		Critical barriers in place	0.016
7/25/2019	2:00	Break Room at F-9		Clean	0.006
	2:05	Warehouse at C-9		Fireproofing, cardboard	0.007
	2:04	Entry to File Stack removal area		Critical barriers in place	0.006
	2:02	Cubicle Area at J-9	Carpeted	0.009	
	2:11	West Egress Hall at J-11	Critical barriers in place	0.020	

Particulate Readings Log
 Bldg. 104 -VA File Demo

	2:12	West Egress Hall at J13	(b) (7)(F)	Critical barriers in place	0.016
	2:08	West Egress Hall at J09		Critical barriers in place	0.005
	2:09	West Egress Hall at J10		Critical barriers in place	0.015
	2:13	West Egress Hall at J15		Critical barriers in place	0.031
7/26/2019	9:33	Break Room at F-9		Clean	0.003
	9:39	Warehouse at C-9		Fireproofing, cardboard	0.005
	9:37	Entry to File Stack removal area		Critical barriers in place	0.005
	9:35	Cubicle Area at J-9		Carpeted	0.004
	9:45	West Egress Hall at J-11		Critical barriers in place	0.018
	9:47	West Egress Hall at J13		Critical barriers in place	0.015
	9:41	West Egress Hall at J09		Critical barriers in place	0.005
	9:43	West Egress Hall at J10		Critical barriers in place	0.016
8/2/2019	10:08	West Egress Hall at J13		Critical barriers in place	0.034
	9:59	Break Room at F-9		Clean	0.003
	10:04	Warehouse at C-9		Fireproofing, cardboard	0.006
	10:00	Entry to File Stack removal area		Critical barriers in place	0.004
	10:02	Cubicle Area at J-9		Carpeted	0.004
	13:09	West Egress Hall at J13		Critical barriers in place	0.024
	13:13	Break Room at F-9	Clean	0.002	
	13:14	Warehouse at C-9	Fireproofing, cardboard	0.002	
	13:16	Entry to File Stack removal area	Critical barriers in place	0.003	
	13:15	Cubicle Area at J-9	Carpeted	0.005	

Particulate Readings Log
 Bldg. 104 -VA File Demo

			(b) (7)(F)		
8/6/2019	15:10	Break Room at F-9		Clean	0.012
	15:12	Warehouse at C-9		Fireproofing, cardboard	0.013
	15:14	North Entrance to Stack Area		Clean	0.017
	15:17	VA Office Cubicle area at J-9		Carpeted, fabrics, etc.	0.020
	15:19	West Egress Hall at J-11		Noted critical barrier to north wall is loose	0.005
	15:22	West Egress Hall at J-12		Noted critical barrier to north wall is loose	0.008
8/13/2019	11:14	Break Room at F-9		Clean	0.036
	11:17	Warehouse at C-9		Fireproofing, cardboard dust	0.040
	11:20	North Entrance to Stack Area		Clean	0.007
	11:24	VA Office Cubicle area at J-9		Carpeted, fabrics, etc.	0.030
	11:28	West Egress Hall at J-11		Noted critical barrier to north wall is loose. Demo is now south of the J line	0.003
	11:32	West Egress Hall at J-12		Noted critical barrier to north wall is loose. Demo is now south of the J line	0.009
8/14/2019	15:02	Break Room at F-9		Clean	0.023
	15:04	Warehouse at C-9		Fireproofing, cardboard dust	0.009
	15:07	North Entrance to Stack Area	Clean	0.015	
	15:08	VA Office Cubicle area at J-9	Carpeted, fabrics, etc.	0.040	
	15:12	West Egress Hall at J-11	Noted critical barrier to north wall is loose. Demo is now south of the J line	0.006	
	15:14	West Egress Hall at J-12	Noted critical barrier to north wall has been repaired.	0.010	
8/15/2019	8:42	Break Room at F-9	Clean	0.008	
	8:45	Warehouse at C-9	Fireproofing, cardboard dust	0.014	
	8:50	North Entrance to Stack Area	Clean	0.021	

Particulate Readings Log
 Bldg. 104 -VA File Demo

	8:55	VA Office Cubicle area at J-9	(b) (7)(F)	Carpeted, fabrics, etc.	0.031
	9:00	West Egress Hall at J-11		Critical barrier to north wall is in place.	0.017
	9:04	West Egress Hall at J-12		Critical barrier to north wall is in place.	0.024
8/22/2019	7:30	Break Room at F-9		Clean	-0.092
	7:32	Warehouse at C-9		Fireproofing, cardboard dust	-0.087
	7:35	North Entrance to Stack Area		Clean	-0.091
	7:40	VA Office Cubicle area at J-9		Carpeted, fabrics, etc.	-0.089
	7:45	West Egress Hall at J-11		Critical barrier to north wall is in place.	-0.092
8/23/2019	11:00	Break Room at F-9		Clean	-0.089
	11:05	Warehouse at C-9		Fireproofing, cardboard dust	-0.087
	11:08	North Entrance to Stack Area		Clean	-0.090
	11:10	VA Office Cubicle area at J-9		Carpeted, fabrics, etc.	-0.091
	11:15	West Egress Hall at J-11		Critical barrier to north wall is in place.	-0.088